

## Advantech NCG product FAQ

NMC-4001/4005/4006/4007/1008/1001 doesn't support ethtool identify command.

Applicable model list	NMC-4001/4005/4006/4007/1008/1001 NMC module.
Model name version	N/A
Firmware Version	N/A


### Description:

When customer key in following command to identify network port sequence of NMC-4001/4005/4007/4006/1008/1001 NMC module, but NMC module's LED is not blinking after key-in command

```
# ethtool -p eth10
```

### Root cause analysis:

1. From Intel reply, "ethtool -p" only activates speed LED of the network device.
2. Please refer following picture, most Advantech NMC modules only design Link LED in NMC front panel, these NMC module don't have speed LED.



3. It means "ethtool -p" command doesn't help user to identify network port sequence of these NMC module.